L Number			DB	Time stamp
•	335	73/818.ccls.	USPAT;	2003/10/29 14:2
	İ		US-PGPUB	2003/10/29 14.2
	İ		ЕРО; ЛРО;	·]
	1		DERWENT	
				·
-	20244	((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	IBM_TDB	
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	USPAT;	2003/04/07 15:5
		weld\$4 fix\$4 secur\$4))	US-PGPUB;	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ЕРО; ЛРО;	
	1		DERWENT;	
_	16023	((()and vira oakle steel 1)	IBM_TDB	
	10023	(((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/07 15:4
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB;	
	1	Weld34 IIX\$4 secur\$4))) and (housing cas\$4 body packag\$4 structure	ЕРО; ЛРО;	1
		mount\$4 backing assembl\$4)	DERWENT;	
			IBM_TDB	
-	8993	(((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4		2002/04/27
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	USPAT;	2003/04/07 15:4
		weld\$4 fix\$4 secur\$4))) same (housing cas\$4 body packag\$4 structure	US-PGPUB;	
		mount\$4 backing assembl\$4)	EPO; JPO;	1
		mountar backing assembla4)	DERWENT;	
_	15971	//11 : 11 · · · · · · · · · · · · · · · · ·	IBM_TDB	
_	139/1	(((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/07 15:50
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB;	2003/04/07 13.30
		weld\$4 fix\$4 secur\$4))) and (housing case casing body packag\$4	ЕРО; ЛРО;	
		structure mount\$4 backing assembl\$4)	DERWENT;	
		0		
-	375	((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	IBM_TDB	
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	USPAT;	2003/04/07 15:50
		weld \$4 fix \$4 secur\$ 4\\\\\ acres (barries and adder \$4 join \$4	US-PGPUB;	-
		weld\$4 fix\$4 secur\$4))) same (housing cas\$4 body packag\$4 structure	ЕРО; ЛРО;	
ļ		mount\$4 backing assembl\$4)) and 73/\$6.ccls.	DERWENT;	
	710	///d 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	IBM_TDB	
	719	((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/07 15:50
	ľ	observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 ioin\$4	US-PGPUB;	2003/04/07 13.30
]	1	weld\$4 fix\$4 secur\$4))) and (housing case casing body packag\$4	EPO; JPO;	
	ļ	structure mount\$4 backing assembl\$4)) and 73/\$6.ccls.		
İ	[6 ··· · // · · · · · · · · · · · ·	DERWENT;	
ł	77	(((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	IBM_TDB	
}	1	observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	USPAT;	2003/04/08 14:34
		weld\$4 fiv\$4 capy\$4\\\\ capy\$54\\\\\	US-PGPUB;	İ
J		weld\$4 fix\$4 secur\$4))) same (housing cas\$4 body packag\$4 structure	ЕРО; ЛРО;	i
		mount\$4 backing assembl\$4)) and 73/\$6.ccls.) and ceramic	DERWENT;	
	144	////	IBM TDB	
1	144	(((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/08 16:20
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB:	2003/04/08 10.20
		weld\$4 lix\$4 secur\$4))) and (housing case casing body packag\$4	EPO; JPO;	
	:	structure mount\$4 backing assembl\$4)) and 73/\$6.ccls.) and ceramic		
		and ceramic	DERWENT;	
1	0 1	(((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	IBM_TDB	
		detect \$4 determin\$4\ mand (= the act 4 = the act 5 =	USPAT;	2003/04/08 17:28
,		detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 weld\$4 fix\$4	US-PGPUB;	
	1	secur\$4) near6 (pull\$4 push\$4))) same (housing cas\$4 body packag\$4	ЕРО; ЛРО;	
	1 5	structure mount\$4 backing assembl\$4) same ceramic)) and 73/\$6.ccls.	DERWENT;	
	i		IBM_TDB	
	2 ((((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	USPAT;	2003/04/09 15:04
	10	ietects4 determins4) near4 (adhess4 adhers4 joins4 welds4 fivs4		2003/04/08 15:04
	í	secur\$4) near6 (pull\$4 push\$4))) same (housing casse casing body	US-PGPUB;	
	l s	in in it is	ЕРО; ЛРО;	
	ļ S	Dackag\$4 structure mount\$4 backing assemble4)		
	ļ S	packag\$4 structure mount\$4 backing assembl\$4) same ceramic))	DERWENT;	
	F	packag\$4 structure mount\$4 backing assembl\$4) same ceramic))	DERWENT; IBM_TDB	
	6 (cackag\$4 structure mount\$4 backing assembl\$4) same ceramic)) ((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4)	DERWENT;	2003/04/08 16:46
	6 (d	((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4 letect\$4 determin\$4) near4 (adhes\$4 adher\$4 ioin\$4 force strength	DERWENT; IBM_TDB USPAT;	2003/04/08 16:46
	6 (i	((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4 letect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength esist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 push\$4))) same (housing	DERWENT; IBM_TDB USPAT; US-PGPUB;	2003/04/08 16:46
	6 (i	cackag\$4 structure mount\$4 backing assembl\$4) same ceramic)) ((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4)	DERWENT; IBM_TDB USPAT;	2003/04/08 16:46

-	3	3 ((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	LIODAT	
1	İ	detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	USPAT;	2003/04/08 16:0
	ĺ	resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 tesnion\$4 break\$4	US-PGPUB;	.
	İ	push\$4)) and ((ceramic) near4 (housing case casing body packag\$4	ЕРО; ЛРО;	
	1	structure mount\$4 backing assembl\$4))	DERWENT;	
-	130	((lead wire cable strong) mose (4-404 : 04 1	IBM_TDB	
		1 (Comment of the straint) floato (lestiff fillofflot) a observit sensit	USPAT;	2003/04/08 16:1
		detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	US-PGPUB;	
		resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 tension\$4 break\$4	ЕРО, ЛРО;	
		push\$4)) and 73/\$6.ccls.	DERWENT;	
			IBM_TDB	
-	35	1 (1) The same stated iteato (testar inomitorar oncerval ceneral	USPAT;	2003/04/09 16:2
	- 1	detects4 determins4) near4 (bonds4) near6 (pulls4 tensions4 breaks4	US-PGPUB;	2003/04/08 16:2
		push\$4)) and 73/\$6.ccls.	EPO; JPO;	
			DERWENT;	
-	150	(((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	IBM_TDB	
		observ\$4 sens\$4 detect\$4 detect\$4	USPAT;	2003/04/08 16:2
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (bond\$4))) and (housing	US-PGPUB;	
	ľ	case casing body packag\$4 structure mount\$4 backing assembl\$4)) and	ЕРО; ЛРО;	
		73/\$6.ccls.) and ceramic	DERWENT;	
			IBM_TDB	
•	0	(1.54 The capie straid) heard (lest 34 monitor 34 observations of	USPAT;	2003/04/08 16:53
		detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	US-PGPUB;	2003/04/08 10.3
		resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 push\$4)) same (clamp\$4	EPO; JPO;	
		grip\$4) same ceramic		
			DERWENT;	
-	0	((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	IBM_TDB	
		detect \$4 determin\$4) near4 (adhas\$4 adhas\$4 in the constant of the constant o	USPAT;	2003/04/08 17:01
		detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	US-PGPUB;	
		bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 push\$4)) same	ЕРО; ЈРО;	
	j	(clamp\$4 grip\$4) same ceramic	DERWENT;	
	7.		IBM_TDB	
-	74	(Code who done stand) nearo (testas monitoras observas sensia	USPAT;	2003/10/29 13:10
	ļ	detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	US-PGPUB;	2003/10/27 13.10
		bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 push\$4)) same	ЕРО; ЛРО;	
		(clamp\$4 grip\$4)	DERWENT;	
				i
-	209	73/827.ccls.	IBM_TDB	2002/10/20 11:55
			USPAT;	2003/10/29 14:29
	İ		US-PGPUB;	
	1		ЕРО; ЛРО;	
	İ		DERWENT;	
	81	73/830.ccls	IBM_TDB	
	01	737830.CCIS.	USPAT;	2003/10/29 14:29
			US-PGPUB,	
			ЕРО; ЛРО;	
	1		DERWENT;	
			IBM_TDB	
	122	73/834.ccls.	USPAT;	2002/10/20 14 20
]			2003/10/29 14:29
	İ		US-PGPUB;	
	İ		ЕРО; ЈРО;	
			DERWENT;	
ļ	3573	((lead wire cable strond)	IBM_TDB	
] 33,3 [((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	USPAT;	2003/04/09 17:52
		detect\$4 determin\$4) near6 (pull\$4 push\$4))	US-PGPUB;	
			ЕРО; ЈРО;	
			DERWENT;	
	į į			
	31	(73/827.ccls. 73/830.ccls. 73/834.ccls.) and ((lead wire cable strand)	IBM_TDB	2002/04/22 := :
		near6 (test\$4 monitor\$4 observ\$4 sens\$4 detect\$4 determin\$4) near6	USPAT;	2003/04/08 17:33
		(pull\$4 push\$4))	US-PGPUB;	
		(L Laneth 1))	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	

-	103	((lead wire cable strand) poors (tortes		4
		((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	USPAT;	2003/04/09 17:5
		detect\$4 determin\$4) near6 (pull\$4 push\$4)) and (bolt\$4 near8 nut)	US-PGPUB:	
	1		ЕРО; ЛРО;	
			DERWENT	.
	1 ,,,		IBM_TDB	'
•	1111	((lead wire cable bond\$4 strand) near6 (test\$4 monitor\$4 observ\$4	USPAT;	2003/04/09 17:5
	ł	sensia detects determins near (pulls pushs 1) and (bolt 4 near 8	US-PGPUB;	2003/04/09 17:5
	1	nut)	ЕРО; ЛРО;	
	İ		DERWENT;	
-	10	("5085084" "6230569" "4677370" "5753823" "5836071").pn.	IBM_TDB	1
	1	ээээээ ээээгт угриг	USPAT;	2003/04/09 19:4
			US-PGPUB;	
			ЕРО; ЛРО;	
	!		DERWENT;	
-	5	("5085084" "6230560" "4627270" "5772200" "577	IBM_TDB	
-	361	("5085084" "6230569" "4677370" "5753823" "5836071").pn.	USPAT	2003/04/09 19:40
	301	((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 asses\$4	USPAT;	2003/10/29 14:2
		measur\$4 meter\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4	US-PGPUB;	
		Johns Torce strength bonds4 resists 4 welds 4 fix \$4 secur\$ 1) near	ЕРО; ЛРО;	
		(Pull 34 push 34 force load \$4)) and ((clamp \$4 hold \$4 secure 4 aring 4)	DERWENT;	
		near4 (base package board substrate))	IBM_TDB	j
•	15	(((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 asses\$4	USPAT;	2002/10/20 14 20
	1	measury4 metery4 sensy4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4		2003/10/29 14:22
		Joint 101ce strength bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) page	US-PGPUB;	1
	i	(pull\$4 push\$4 force load\$4)) and ((clamp\$4 hold\$4 secur\$4 grip\$4)	ЕРО; ЈРО;	
		near4 (base package board substrate))) and braz\$4	DERWENT;	
	346	73/818.ccls.	IBM_TDB	
			USPAT;	2003/10/29 14:37
			US-PGPUB;	
	J		ЕРО; ЛРО;	
			DERWENT;	
į	216	73/827.ccls.	IBM_TDB	
j	210	73/827.CCIS.	USPĀT;	2003/10/29 14:29
]			US-PGPUB;	2003/10/27 14.27
j			ЕРО; ЛРО;	ļ
ĺ			DERWENT;	
İ			IBM_TDB	
i	83	73/830.ccls.	USPAT;	2002/10/20 14 22
			•	2003/10/29 14:29
	1		US-PGPUB;	
			EPO; JPO;	
	1		DERWENT;	
	123	73/834.ccls.	IBM_TDB	
			USPAT;	2003/10/29 14:29
			US-PGPUB;	
			ЕРО; ЈРО;	
			DERWENT;	
	12	72/9191- 72/927 1 72/92	IBM_TDB	
1	13 (73/818.ccls. 73/827.ccls. 73/830.ccls. 73/834.ccls.) and (((lead wire	USPAT;	2003/10/29 14:38
	"	able strand) nearb (test\$4 monitor\$4 observ\$4 asses\$4 measur\$4	US-PGPUB;	2003/10/27 14.38
	I	neter \$4 sens \$4 detect \$4 determin \$4) near 4 (adhes \$4 adher \$4 ioin \$4)	EPO; JPO;	
	l f	orce strength bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4		
	1			
	P	sush\$4 force load\$4)) and ((clamp\$4 hold\$4 secur\$4 grip\$4) near4 base package board substrate)))	DERWENT; IBM_TDB	